Inventory No.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of F	roperty	(indicate prefe	erred name)					
historic	306 Park Road							
other								
2. Location								
street and number	306 Park Road						not fo	or publication
city, town	Rockville						vicini	ty
county	Montgomery							
3. Owner of	Property	(give names and r	nailing address	ses of a	ll owners)			
name	Husni Kuraishi							
street and number	21208 Virginia	Pine Terrace			tel	ephone		
city, town	Germantown,		state	MD	zip	code	20876-	4382
4. Location	of Legal D	escription						
	_	Montgomery County			liber	folio)	
city, town	Rockville	tax map	GR 42 tax	parcel	Lot 18 & PT	19 tax	ID number	r 04-00163994
Contri Deterr X Deterr Recor Histori	buting Resource i mined Eligible for mined Ineligible for ded by HABS/HA	rt or Research Report	et Maryland Regis r/Maryland Reg					
6. Classifica Category districtbuilding(s)	Ownershippublicprivate	Current Functionagriculturecommerce/t	la tradere		_	Resourc Contribut	ce Count ing N	oncontributing 1 building
structure site object	both	defenseXdomesticeducationfunerarygovernmenthealth careindustry	sctraw tuıx_va	nknown	rogress ot in use N			sites structure objects Total ruting Resources n the Inventory

7. Description		Inventory No.
Condition		
excellent <u>x</u> good fair	deteriorated ruins altered	

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Summary

The house at 306 Park Road was built circa 1937¹. It exemplifies the expansion of residential subdivisions in Rockville on the east side of the railroad tracks, with small residential one-story structures predominating. The original portion of the house, with its modest one-story, L-shaped massing, is still apparent. High quality, and typical, early 20th century building materials were used, including wood German siding and concrete foundation blocks poured to imitate dressed stone. Several additions have been added to the east side and at the rear, and alterations through the years have reduced the impact of the front porch. As this property consists of portions of 3 platted lots, there is extra yard space and mature oak trees that provide shade for the public street.

Description

The property at 306 Park Road includes lots 17, 18 & PT 19 in Block M of the Croydon Park subdivision. Croydon Park was platted in 1924 by Joseph and John G. Reading. The original subdivision map shows Lot 17 (37.39x115.23), Lot 18 (37.38x83.02), and triangular Lot 19 (93.45x83.02x125). Subsequent road and sidewalk construction probably resulted in the reduction of Lot 19 to a partial lot (PT 19). The property is located at the intersection of Park Road with Horner's Lane, and helps turn the corner as Park Road runs into North Horner's Lane. The property has been treated as a unity and the recent side addition crosses lot lines.

The house faces southeast. There is a single driveway into the property, and much of PT 19 is paved for parking. There are two mature oak trees along the east edge of the property, and a single holly directly in front of the main entrance. In addition, there are assorted shrubs around the structure, and trees and shrubs around the perimeter of the property.

The house consists of the main block with a rear ell on the left side, on a "dressed" concrete block foundation, and with wood German siding. There is a full-width front porch with a hipped roof, which may be original, although the columns, decking, rail and steps are clearly recent. The windows were probably originally 6/1, there being several such windows extant in the side ell; but, most of the windows have been replaced with 1/1 light windows. The front door appears to be original, with a ½-light divided into three vertical lights. There are glass sliding doors at the rear, leading out to the back yard. A long, narrow addition was built on the east side, with a separate entrance and entry stoop. At the rear, an original back room that was sheathed with German siding has been expanded into a long, narrow addition with several elements and varying roof configurations. There is a single central brick chimney in the original block.

Landscape Features

¹ Maryland Department of Assessments and Taxation. The parcels were assembled as 17, 18, 19 by George Mills in 1939 and were sold as a unit for the first time on 9/23/39 to Samuel Edwards. The house was likely built at this time.

The house has a grassy front yard and an open left side-yard. The east part of the front and side yard has been paved for a large parking area, leaving a small triangle at the east edge of the property in grass and with the two large mature oak trees. There is virtually no back yard behind the narrow east addition, but the back yard expands to the west, leaving room for a patio and grass behind the original house block with ell. In the NW portion of the yard, there are some landscape ties, including a blocked-out square that may indicate an old well, or an old sewer tap, or simply a garden feature.

The rear property line is delineated with wire fencing, and the left side property line is delineated with wood fencing.

8. Significa	nce Inve	entory No.		
Period	Areas of Significance	Check and	justify below	
1600-1699 1700-1799 1800-1899 1900-1999 2000-	agriculture archeology X architecture art commerce communications community planning conservation	x economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	health/medicine industry invention landscape architectu law literature maritime history military	performing arts philosophy politics/government ure religion science x social history transportation other:
Specific dates			Architect/Builder	
Construction da	ate circa 1937			
Evaluation for:				
	National Register		Maryland Register	not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

History

John Brewer and his wife sold the farmland that included this property in 1884 to William Reading². Upon his death, William Reading's sons, Joseph Reading and John G. Reading, inherited the property. Joseph Reading was a local druggist and a real estate developer, and he was prominent in Rockville, serving as Mayor of Rockville from 1896-98. The Readings' property east of the tracks was annexed by the City in April 1896, but the Croydon Park subdivision³ was platted and recorded in 1924.

Based on the grid established by the earlier subdivision of Rockville Park on the south side of Baltimore Road, the Croydon Park lots extended from Baltimore Road to Crabb Avenue (N-S), and from S. Horner's Lane to the B&O Railroad tracks (E-W). The Railroad station originally sat nearby, at a point just north of the Baltimore Road track crossing. Typical features of the subdivision included 5,000 sf rectangular lots (with some variety of lot size and shape platted to accommodate angles and corners); the use of internal alleys; two pump house sites; and, a public park. The extension of Stonestreet Avenue was platted as "Biltmore" Avenue, but several of the street names recall other local residents (Horner, England, Reading). Croydon Park, in turn, provided the essential street grid for H. L. England's Second Addition to Rockville (1926) to the north and east.

² 16 March 1884, Liber E.B.P. 30/Folio 387, containing ca. 60 acres.

³ Plat #272

Lots 17, 18, and 19 were sold by John G. Reading individually in the 1930's to George O. Mills. Mr. Mills speculated in land in the Croydon Park Subdivision, The day after buying Lot 19, Mr. Mills sold all three lots to Samuel and Blanche Edwards. It is likely that the house was constructed at this time, because of the location of the house with respect to lot lines. The Edwards raised their family here, and the property was sold by their children after their death to Charles P. and Eleanor B. Atwood. The Atwoods were less lucky in their residence here, for Mrs. Atwood died the next year, and Mr. Atwood died in 1971. After his death, their children sold the property to the Kamlots.

The city's early utility records confirm the identity of these early resident by listing the year when a particular family began to pay the utilities: S.E. & Blanche E. Edwards 1939; Charles P & E. B. Atwood in 1966; and Lawrence & J. C. Kamlot in 1972. The current owners, Husni and A. M. Kuraishi, purchased the property in 1990, although the records indicate they were paying utilities there from 1987. The property has been rented in the recent years.

Significance

The Croydon Park neighborhood was found not eligible for the National Register of Historic Places in an evaluation that was undertaken for the Maryland Historical Trust by P.A.C. Spero & Co in 1998. The evaluation states that the neighborhood fails to meet any of the National Register criteria: it lacks association with historic events or trends of national, state, or local history (A); it lacks association with a person who made specific contributions to history (B); the building does not represent significant building types, and lacks integrity due to additions and alterations (C); and, there is no known potential to yield important information (D).

The Croydon Park subdivision, however, is part of a national trend with roots in the mid-19th century cottage ideal of Downing. Through the years, and with the development of new modes of transportation, the suburban ideal eventually included residential development for people of modest means. The platting of the acreage into a large number of small lots provided flexibility for individuals to buy a large or small property depending on their means. This flexibility was not readily available in earlier subdivisions where the original acreage was subdivided into large lots, as in Reading's 1st Addition to Rockville (1888). When this was resubdivided as Rockville Park in 1890, the new developer provided the larger number of smaller lots, thereby increasing the flexibility for buyers. This pattern was followed by the Readings with the Croydon Park subdivision 34 years later. This provided people of modest means an opportunity to engage both in property ownership, and to define the property for their single-family residence that was affordable for them.

The vernacular cottage at 306 Park Road illustrates this local development pattern, with the purchase of multiple lots for the single residence. In the case of 306 Park Road, the original owners purchased 3 lots (17, 18 and 19), and constructed their house towards the center of the property, leaving large side yards. They also constructed a small 1-story shed in the NW corner area of the property.

⁴ 560/148, 9/22/33, John G. Reading sells Lot 18 to George O. Mills, with a deed restriction that the land would not be sold to persons of African descent; 728/27, 2/21/39, John G. Reading sells lot 19 to George O. Mills. 728/85, 2/23/39, George O. Mills sells 17, 18, 19 to Samuel E. Edwards.

⁵ Amongst other purchases, he bought 5 lots in Block H,728/95, 2/23/39.

⁶ 3469/621, 2/4/1966.

⁷ 4099/517, 7/9/71. The property was valued at \$16,000 in the estate papers (Will Case #0130171).

⁸ See Olmstead's work with railroad suburbs, and FLWright's proposition for low-rise development across the US.

⁹ Sanborn Maps 1949, 1960

¹⁰ Sanborn Maps 1949

In a local historic district, 306 Park Road might be considered a "Contributing" resource with many alterations, and would probably be categorized as somewhere between "Minor alterations" and "Substantially altered," on the HDC's Historic Designation Criteria Checklist. Despite the many additions and alterations, one can still discern the original massing, materials, and design, and environmental setting. There is, however, a loss of integrity: one notes the loss of the setting, with the paving over of 1/3 of the site; there is a loss of historic materials and details, including original windows, and the front porch; and the original massing has been compromised with the side addition, side entrance, and all of the rear additions. While much of the original site could be reconstructed with the removal of the incompatible additions, the installation of new 6/1 wood windows, the construction of a new porch, and the removal of the asphalt parking area, this could not replace historic materials and therefore, could not restore lost integrity.

Staff Recommendation

On the basis of lack of integrity, staff recommends that this site fails to meet the HDC's Criteria for listing as a an individual historic district. There is concern about the impact of the demolition of these early 20th century residences on the neighborhood, and on the future possibility of designating a multi-property historic district. Further, there is concern with the construction of multiple homes on a property that originally had only one house, which increases the neighborhood population density and results in the loss of garden space around the homes. The effect on the neighborhood can be softened by building homes that reflect those in the existing neighborhood: three-bedroom, one to one-and-1/2 story buildings, with a clear relationship to the yard (having no more than 5 entry steps), and with a garage that has minimal impact on the view from the street by pushing it to the back of the property.

Quadrangle scale:

Lot 17, Lot 18, and PT Lot 19 of Block M in Croydon Park subdivision

11. Form Prepared by

name/title	Robin D. Ziek	
organization	City of Rockville, HDC staff	date 10-23-03
street & number	111 Maryland Avenue	telephone 240-314-8236
city or town	Rockville	state MD

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

> Maryland Historical Trust return to:

DHCD/DHCP

100 Community Place Crownsville, MD 21032-2023

410-514-7600



Public view (south) of Property



Front (south) elevation



Side (west) elevation



Rear (north) elevation



Side (southwest) view



Side (east) elevation of east addition



Front porch looking west

6/1 windows on side ell (west elevation)





"Dressed" Concrete Foundation blocks, and German siding



